

GOVERNMENT OF WEST BENGAL
OFFICE OF THE BLOCK MEDICAL OFFICER OF HEALTH
MURADIH B.P.H.C ,PO-MURADIH, PS-SANTURI, PIN-723156
DIST-PURULIA

Memo No:- MURADI(SNT)-84.

Date:-30-08-2024

TO WHOM IT MAY CONCERN

This is to certified that, DAV Public School, Madhukunda Located at ACC Damodhar Cement Work Campus, PO- Sunuri, Dist-Purulia, has safe drinking water facilities(as per PHE report) for the student and members of staff on the institution and maintaining the hygienic sanitation condition in the school building & the campus norms prescribed by the central/State Govt.

C. J. S.
30/8/2024
Block Medical Officer of Health
Muradih B.P.H.C
Po- Muradih, Dist- Purulia
Block Medical Officer of Health
Muradih B.P.H.C, P.O.- Muradih
Purulia

Santuri Sub District Water Testing Laboratory
Under
PURULIA DIVISION
PUBLIC HEALTH ENGINEERING DIRECTORATE
GOVT OF WEST BENGAL
Santuri Purulia

Water Testing Report

Date of collectionn : 20.08.2024	Collection By : Saibal Biswas (Teacher)
Analysis started on : 20.08.2024	Place of sample : DAV Public School (Madhukunda)
Analysis completed : 21.08.2024	Type of sample : boring

Sl No	Parameters	Unit	Desirable Limit As per BIS	Permissible Limit As per BIS	Test Result
A	Physical And Chemical Result				
1	Temperature	Oc			29.2
2	Turbidity	NTU	1	5	3.96
3	pH		6.5	8.5	7.11
4	Total Hardness	Mg/lit	200	600	228
5	Iron	Mg/lit	0.3	1	0.34
6	Residual Chlorine	Mg/lit	0.1	0.2	0.2
7	Fluoride	Mg/lit	1	1.5	0.11
B	Bacteriological Result				
1	TC	CFU/100ml	Absent	Absent	Absent
2	FC	CFU/100ml	Absent	Absent	Absent

Safe Drinking Water

Ais *Am* 22.08.24
Chemist

Santuri Sub District Water Testing Laboratory
Chemist / Bacteriologist
Santuri Water Testing Laboratory